











EMT Cartridges

2018




Country: EU
VAT: 20.00%

#	Name	Description		Retail EUR
9 937 070	JSD P6.0	EMT Jubilee Series MC cartridge Diamond on sapphire cantilever Bronze body, Platinum coated		4'130.00
9 937 077	JSD VM	EMT Jubilee Series MC cartridge Diamond on sapphire cantilever Variable Mass body		3'770.00
9 937 078	JSD Lime	EMT Jubilee Series MC cartridge Diamond on sapphire cantilever Sandwich body, lime anodized		3'650.00
9 937 075	JSD S75	EMT Jubilee Series MC cartridge Diamond on sapphire cantilever Aluminium body, black anodized		3'520.00
9 937 000	JSD 5	EMT Jubilee Series MC cartridge Bor cantilever, Gyger S Aluminium body, anodized		2'670.00
9 937 001	JSD 6	EMT Jubilee Series MC cartridge Bor cantilever, SFL Aluminium body, anodized		2'430.00
9 935 406	HSD 006	EMT Stereo MC Cartridge Aluminium Cantilever, SFL Aluminium body, red anodized		1'220.00
9 935 425	HMD 025	EMT Mono MC Cartridge Aluminium Cantilever, SPH 25 Aluminium body, blue anodized		1'090.00
Repair I	Refurbishment Service JSD Sapphire	New transducer unit New damping unit Alignment service		1'650.00
	Refurbishment Service JSD 5			1'290.00
	Refurbishment Service JSD 6			1'100.00
	Refurbishment Service HSD 006			640.00
	Refurbishment Service HMD 025			550.00
Repair II	Refurbishment Damping	New damping unit Alignment service		460.00

EMT Cartridges

2018

Country: EU
VAT: 20.00%

#	Name	Description		Retail	EUR
9 935 000	TSD 15 SFL	Typ: Stereo SFL Connection: EMT		1'180.00	
9 935 033	TSD 15 SPH	Typ: Stereo SPH 15 Connection: EMT			
9 935 008	XSD 15 SFL	Typ: Stereo SFL Connection: SME		1'180.00	
9 935 034	XSD 15 SPH	Typ: Stereo SPH 15 Connection: SME			
9 935 003	TMD 15	Typ: Mono SPH 15 Connection: EMT		1'100.00	
9 935 001	TMD 25	Typ: Mono SPH 25 Connection: EMT			
9 935 002	TMD 65	Typ: Mono SPH 65 Connection: EMT			
Repair I	Refurbishment Service Tondose Stereo	New transducer unit New damping unit Alignement service		770.00	
	Refurbishment Service Tondose Mono			730.00	
Repair II	Refurbishment Damping	New damping unit Alignement service		410.00	

PS AUDIO SCANDINAVIA www.psaudio.dk

Der tages forbehold for tryk- og tastefejl, prisændringer og udsolgte varer.